

JAMES E. RISCH – Governor RICHARD M. ARMSTRONG – Director DEBBY RANSOM, R.N., R.H.I.T - Chief BUREAU OF FACILITY STANDARDS 3232 Elder Street P.O. Box 83720 Boise, Idaho 83720-0036 PHONE: (208) 334-6626 FAX: (208) 364-1888 E-mail: fsb@idhw.state.id.us

October 6, 2006

Linda Biain, Administrator Cenoma House 1930 Heyburn Avenue East Twin Falls, ID 83301 FILE COPY

License #: RC-479

Dear Ms. Biain:

On September 5, 2006, a life safety code survey was conducted at Cenoma House. As a result of that survey, deficient practices were found. The deficiencies were cited at the following level(s):

• Non-core issues, which are described on the Punch List, and for which you have submitted evidence of resolution.

This office is accepting your submitted evidence of resolution.

Should you have questions, please contact Eric Mundell, Health Facility Surveyor, Facility Fire, Life Safety, and Construction Program, at (208) 334-6626.

Sincerely,

ERIC MUNDELL

Health Facility Surveyor

Facility Fire, Life Safety, and Construction Program

EM/slc

c:

Mark Grimes, Supervisor, Facility Fire, Life Safety, and Construction Program

JAMES E. RISCH -- Governor RICHARD M. ARMSTRONG -- Director DEBBY RANSOM, R.N., R.H.I.T – Chief BUREAU OF FACILITY STANDARDS 3232 Elder Street P.O. Box 83720 Boise, Idaho 83720-0326 PHONE: (208) 334-6262 FAX: (208) 364-1888 E-mail: fsb@idhw.state.id.us

September 13, 2006

Linda Biain, Administrator Cenoma House 1930 Heyburn Avenue East Twin Falls, ID 83301 FILE COPY

Dear Ms. Biain:

On September 5, 2006, a life safety code survey was conducted at Cenoma House. The facility was found to be providing a safe environment for its residents.

The enclosed form, stating no core issue deficiencies were cited during the survey, is for your records only and need not be returned.

Please bear in mind that non-core issue deficiencies were identified on the punch list, a copy of which was reviewed and left with you during the exit conference. The completed punch list form and accompanying proof of resolution (e.g., receipts, pictures, policy updates, etc.) are to be submitted to this office by October 5, 2006.

Should you have any questions about our visit, please contact me at (208) 334-6626.

Sincerely,

MARK GRIMES

Supervisor

Facility Fire Safety & Construction Program

MG/slc

Enclosure

**Bureau of Facility Standards** 

STATEMENT OF DEFICIENCIES (X3) DATE SURVEY (X1) PROVIDER/SUPPLIER/CLIA (X2) MULTIPLE CONSTRUCTION AND PLAN OF CORRECTION COMPLETED **IDENTIFICATION NUMBER:** 01 - ENTIRE BUILDING A. BUILDING B. WING\_ 13R479 09/05/2006 STREET ADDRESS, CITY, STATE, ZIP CODE NAME OF PROVIDER OR SUPPLIER **1930 HEYBURN AVENUE EAST CENOMA HOUSE** TWIN FALLS, ID 83301 SUMMARY STATEMENT OF DEFICIENCIES PROVIDER'S PLAN OF CORRECTION (X4) ID (X5) COMPLETE DATE (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE (EACH DEFICIENCY MUST BE PRECEDED BY FULL PRÉFIX PREFIX REGULATORY OR LSC IDENTIFYING INFORMATION) TAG TAG DEFICIENCY) R 000 Initial Comments R 000 The facility was found to be in substantial compliance with the fire and life safety standards of the Rules for Residential or Assisted Living Facilities in Idaho. No core deficiencies were cited during the standard fire/life safety survey conducted on Sept 5, 2006. The surveyors conducting the survey were: Eric Mundell Team Leader Health Facility Surveyor Chris Laumann Fire/ Life Safety Surveyor **Bureau of Facility Standards** 

LABORATORY DIRECTOR'S OR PROVIDER/SUPPLIER REPRESENTATIVE'S SIGNATURE

STATE FORM 6899

QV5Z21

TITLE

If continuation sheet 1 of 1

(X6) DATE



## BUREAU OF FACILITY STANDARDS P.O. Box 83720 Boise, ID 83720-0036 (208) 334-6626 fax: (208) 364-1888

## ASSISTED LIVING Non-Core Issues Punch List

Facility Name			Physical Address	Phone Number
<u>Cenona</u>   Administrator	nou se		1930 Heyburn Ave E.	(208) 736-747
	and the second s		City	ZIP Code
Chas 4	-aun	ann	Twin Falls	83301
Survey Team Leader			Survey Type	Survey Date
			Fire/ Life Safety	S Sept 200
NON-CORE ISSUES				
ITEM RU	LE#		DESCRIPTION	DATE RESOLVED
/ 16.03.	Q).750.0i	Fire Drill Docc	imentation: No Fre drills	have
		Geen Nocum	sented since March. 2006.	
2 16,03,0	a.465.01,	B Electrical:	the extension cord was	Round
	**.	60 Lad 7010.	vision in living roung	9 m
		An electrical	(multiple electrical) o	adapter-
		was found	in room three.	•
			restau. Vid	
		· ·		
				00100000000000000000000000000000000000
and the same of th		Signature of Facility Representative		
500 a	M	Datra Danelys	Ti Walan	